

WIRELESS DESKBIKE COMPUTER

Office chair out...DeskBike in!



Deskbike

Display manual

Turn on the Display

- Press the **on/off** button
- Press **connect**

New connection

- Start cycle
- Press the **on/off** button
- Press **connect**. KCAL + TIME will flash
- Hold the display at the deskbike adjustment knob. After 10 seconds the meters must run
- Place the display on your worksheet and bike!

Bring display to 0

- Press 1 time on **reset**
- Press 1 time on **on/off**

Connect display with other deskbike / full reset

- Press the **on/off** button
- Press 5 seconds on the **reset** button. You will see CL+
- Press 1 time on **connect**
- Now bring the display to your deskbike. The meters will run when it's connected